



AHERA THREE – YEAR REINSPECTION



***Field
Services***

For:

**Boyertown Area School District
1131 Montgomery Avenue
Boyertown, PA 19512**

Prepared By:

PREPARED BY:

A handwritten signature in black ink, appearing to read 'Michael Barth', written over a horizontal line.

**Michael Barth
Building Inspector, Management Planner
License # 059566**



***Lab
Services***

Report Date:

July 31, 2024

Project Number:

241801

Date(s) of Project:

July 8, 2024 – July 15, 2024



***Training
Services***

SECTION A

COVER LETTER



July 30, 2024

Boyertown Area School District
1131 Montgomery Avenue
Boyertown, PA 19512

ATTENTION: Ms. Kelly Elliot
Facilities & Maintenance Administration

REFERENCE: AHERA Reinspection
Boyertown Area School District
Criterion's Project Number **241801**

Dear Ms. Elliot,

Starting July 8, 2024, a Pennsylvania-licensed and U.S. E.P.A.-certified building inspector from Criterion Laboratories, Inc. (Criterion) completed the AHERA three-year reinspection of the Boyertown Area School District (BASD) in Boyertown, Pennsylvania. All identified and assumed asbestos-containing materials (ACM) were visually reinspected according to AHERA regulation 40 CFR Part 763 to determine their condition. If a change in condition had taken place since the 2021 AHERA reinspection, the material was reassessed and assigned into the appropriate category in accordance with AHERA regulations.

The response actions and assessment forms for each school/building containing ACM are attached. We recommend that the response actions be followed as stated.

If you should have any questions, please do not hesitate to contact me at (215) 244-1300, extension 1051.

Sincerely,

A handwritten signature in black ink, appearing to read 'Michael Barth', with a horizontal line underneath.

Michael Barth
Pennsylvania-licensed Building Inspector
And Management Planner
License Number 059566

SECTION B

RESPONSE ACTIONS / ASSESSMENT FORMS



RESPONSE ACTIONS/ASSESSMENT SHEETS

RESPONSE ACTIONS

LEA: Boyertown Area School District

SCHOOL: Boyertown Elementary School

LOCATION AND DESCRIPTION	RESPONSE ACTION
Blackboard Adhesive – Classrooms 104, 105, 106, 107, 108, 115, 118, 121, 122, 125, 126, 127, 128, 143, 144, 145, 146, 147, 155, 156, 157, 158, 173, 177, 182, 183, 184, 185, 186, 187, 188, 196, 197, 199, 201, 203, 205	Operations & Maintenance (O&M), Assumed – Sample prior to removal
HVAC Cloth Expansion Joint – Mechanical Room 222	O&M
Fire Doors – Mechanical Room, Custodial Receiving	O&M. Assumed
12”x12” Floor Tile and Mastic - Multi-purpose room, Gymnasium, Gymnasium office, Stage, Storage 242, Storage 245, Room 224, Room 173 IT, Room 173 ESL, Storage 147, Storage 149, Storage 150, Room 114 Library Office, Room 115, Storage 122, Storage Rooms between 118 and 121, Storage Rooms between 177 and 182	O&M Repair damaged tiles – See AHERA Assessment Forms for detailed locations



Environmental & Industrial Hygiene

Field Services. . .
Laboratory Services.

Training. . .
. . . **Solutions**

RESPONSE ACTIONS

LEA: **Boyertown Area School District**

SCHOOL: **Boyertown High School**

LOCATION AND DESCRIPTION	RESPONSE ACTION
Fire Doors – Stairwell #1, 2 nd Floor, Stairwell #1, 3 rd Floor	Operations & Maintenance (O&M)



Environmental & Industrial Hygiene

Field Services. . .
Laboratory Services.

Training. . .
. . . **Solutions**

RESPONSE ACTIONS

LEA: **Boyertown Area School District**

SCHOOL: **Boyertown Middle School East**

LOCATION AND DESCRIPTION	RESPONSE ACTION
Fire Doors – Boiler Room, Mechanical Room, 522-Loading Dock, 520, 516 - Storage, 517 - Storage	O&M
Acoustical Ceiling Plaster – Planetarium	O&M



Environmental & Industrial Hygiene

Field Services. . .
Laboratory Services.

Training. . .
. . . **Solutions**

RESPONSE ACTIONS

LEA: Boyertown Area School District

SCHOOL: Boyertown Middle School West

LOCATION AND DESCRIPTION	RESPONSE ACTION
Fire Doors – Loading Dock, Boiler Room	O&M, Assumed
Blackboard Adhesive – Rooms 19, 20, 21, 23, 24, 25, 26, 27, 28, 29, 32, 33, 34, 35, 36, 37, 38, 39, 40, 42, 43, 44, 45, 46, 47, 47.1, 48, 61, 62, 63, 64, 70, Band Room	O&M, Assumed – Sample prior to removal



RESPONSE ACTIONS

LEA: Boyertown Area School District

SCHOOL: Colebrookdale Elementary School

LOCATION AND DESCRIPTION	RESPONSE ACTION
Transite Windowsills – Throughout Building	O&M, Assumed
Transite Skylights – Corridor Outside Library	O&M, Assumed – Sample prior to removal
Transite Panels – Multi-purpose Room	O&M, Assumed – Sample prior to removal
Fire Doors – Boiler Room, Maintenance Room	O&M
Blackboard Adhesive - 101, 102, 103 Art-Room, Hallway outside Library, 100, 201, 202, 203, 204, 205, 206, 207, 208, 210, 211, 212, 301, 302, 303, 304, Guidance office, Conference room	O&M, Assumed – Sample prior to removal



Environmental & Industrial Hygiene

Field Services. . .
Laboratory Services.

Training. . .
. . . **Solutions**

RESPONSE ACTIONS

LEA: **Boyertown Area School District**

SCHOOL: **Earl Elementary School**

LOCATION AND DESCRIPTION

RESPONSE ACTION

Plaster Ceiling – Boiler Room

O&M, Repair, Assumed – Sample prior to removal



Environmental & Industrial Hygiene

Field Services. . .
Laboratory Services.

Training. . .
. . . **Solutions**

RESPONSE ACTIONS

LEA: **Boyertown Area School District**

SCHOOL: **Education Center**

LOCATION AND DESCRIPTION	RESPONSE ACTION
Floor Tile and Mastic – Old Mail Room, Data Processing, Lunchroom, Vault Room	O&M, Repair damaged tiles – See AHERA Assessment Forms for detailed locations
Fire Doors – Boiler Room, Vault Room	O&M, Assumed



RESPONSE ACTIONS

LEA: Boyertown Area School District

SCHOOL: Gilbertsville Elementary School

LOCATION AND DESCRIPTION	RESPONSE ACTION
Floor Tile and Mastic – Under Walls	O&M, Assumed – Sample prior to removal
Fire Doors – Boiler Room, Room outside Boiler Room, Music Room Corridors, Basement Rooms	O&M, Assumed – Sample prior to removal
HVAC Cloth Expansion Joint – Boiler Room	O&M, Assumed – Sample prior to removal
Blackboard Adhesive - 111, 112, 113, 114, SGI room, 121, 122, 123, 124, Reading Room - Room 26, Faculty Lounge, 124, 28, 30, 31, Reading room adj. to Rm 30, 131, 132, 133, 134, 135, 136 computer room, 130, 137-D, 141, 142, Faculty Dining, 143, 144, Kindergarten 1, Kindergarten 2, 151, 152, 153, 154, 161, 162, 163, 164, Library, Music Room, Instrumental Music, Water Tank Room Next to Boiler Room	O&M, Assumed – Sample prior to removal



Environmental & Industrial Hygiene

Field Services. . .
Laboratory Services.

Training. . .
. . . **Solutions**

RESPONSE ACTIONS

LEA: Boyertown Area School District

SCHOOL: Pine Forge Elementary School

LOCATION AND DESCRIPTION	RESPONSE ACTION
Blackboard Adhesive – 700A, 700B, 701, 702, 703, 704, 705, 706, 707, 708, 709, 711, 713, 715, 717, 719, 721, 722, 724, 726, Library Offices, Guidance, Instrument Room, Faculty Room 3	O&M, Assumed – Sample prior to removal
Floor Tile and Mastic – Corridors outside Main Office, TV Studio (little room), Corridor outside Room 702	O&M



Environmental & Industrial Hygiene

Field Services. . .
Laboratory Services.

Training. . .
. . . **Solutions**

RESPONSE ACTIONS

LEA: Boyertown Area School District

SCHOOL: Support Services Building

LOCATION AND DESCRIPTION	RESPONSE ACTION
Plaster Wall and Ceiling – Throughout 1st Floor, Basement Shop Area	O&M, Repair, See AHERA Assessment Forms for detailed locations, Assumed – Need To Sample
Floor Tile and Mastic – Quigley Bus Office, Transportation Offices, Secretary's Office, Supervisor's Office, Bathroom, Entrance Foyer, Bathroom	O&M, Repair, See AHERA Assessment Forms for detailed locations, Assumed – Need To Sample



Environmental & Industrial Hygiene

Field Services. . .
Laboratory Services.

Training. . .
. . . **Solutions**

RESPONSE ACTIONS

LEA: **Boyertown Area School District**

SCHOOL: **Washington Elementary**

LOCATION AND DESCRIPTION	RESPONSE ACTION
Blackboard Adhesive – Storage room, 9, 10, 12, 13, 23, 24, 48, 49, 51, 52, 53, 54, 55, 56, 57, 58, 60, 111, 112, 113, 114, 121, 122, 123, 124, 131, 132, 133, 134, 141, 142, 143, 144, 151, 152, 153, 154, 161, 162, 163, 164	O&M, Assumed – Sample Prior to Removal
Fire Door – Boiler Room, Room 12, Corridors	O&M, Assumed – Sample Prior to Removal

**AHERA REINSPECTION
ASSESSMENT FORM**

Inspector Signature: CJ Karoly Project Number: 241801

Accreditation ID Number: 059567 Inspection Date: 7/8/2024

Building: Boyertown Elementary School Homogenous Area: Fire Doors

Sample Numbers: N/A Homogenous Area I.D. Number: N/A

Friable: yes Total Quantity: 7 EA

ACBM by: N/A Result: N/A

Classify ACBM and suspected ACBM assumed to be ACM into one of the following categories:

Category	Type Of Material	Condition
<input type="checkbox"/> 1a.	Thermal System Insulation ACM	Damaged
<input type="checkbox"/> b.	Thermal system Insulation ACM	Significantly Damaged
<input type="checkbox"/> 2.	Friable ACM Surfacing Material	Damaged
<input type="checkbox"/> 3.	Friable ACM Surfacing Material	Significantly Damaged
<input type="checkbox"/> 4a.	Friable ACM Miscellaneous	Damaged
<input type="checkbox"/> b.	Friable ACM Miscellaneous	Significantly Damaged
<input type="checkbox"/> 5.	ACBM	Potential for Damage
<input type="checkbox"/> 6.	ACBM	Potential for Significant Damage
<input checked="" type="checkbox"/> 7.	Friable ACBM or Friable Suspected ACBM	Undamaged
<input type="checkbox"/> 8.	Non-Friable ACBM or Non-Friable Suspected ACM	

List General Functional Spaces e.g., Classrooms, Gym, Lunchroom

Mechanical room, Custodial Receiving

General Condition of Entire Homogenous Area: Good Accessibility: Limited

Potential For Disturbance: Limited Damage: N/A

Type of Damage: N/A

Percent over Entire Homogenous Area: N/A Known or Suspected Cause: N/A

Preventative Measures: N/A

**AHERA REINSPECTION
ASSESSMENT FORM**

Inspector Signature: CJ Karoly Project Number: 241801
 Accreditation ID Number: 059567 Inspection Date: 7/8/2024
 Building: Boyertown Elementary School Homogenous Area: Floor tile
 Sample Numbers: N/A Homogenous Area I.D. Number: N/A
 Friable: No Total Quantity: 3120 SF
 ACBM by: N/A Result: N/A

Classify ACBM and suspected ACBM assumed to be ACM into one of the following categories:

Category	Type Of Material	Condition
<input type="checkbox"/>	1a. Thermal System Insulation ACM	Damaged
<input type="checkbox"/>	b. Thermal system Insulation ACM	Significantly Damaged
<input type="checkbox"/>	2. Friable ACM Surfacing Material	Damaged
<input type="checkbox"/>	3. Friable ACM Surfacing Material	Significantly Damaged
<input type="checkbox"/>	4a. Friable ACM Miscellaneous	Damaged
<input type="checkbox"/>	b. Friable ACM Miscellaneous	Significantly Damaged
<input type="checkbox"/>	5. ACBM	Potential for Damage
<input type="checkbox"/>	6. ACBM	Potential for Significant Damage
<input type="checkbox"/>	7. Friable ACBM or Friable Suspected ACBM	Undamaged
<input checked="" type="checkbox"/>	8. Non-Friable ACBM or Non-Friable Suspected ACM	

List General Functional Spaces e.g., Classrooms, Gym, Lunchroom

Multi Purpose Room

General Condition of Entire Homogenous Area: Good Accessibility: Limited
 Potential For Disturbance: Limited Damage: 2 SF
 Type of Damage: 2 broken tiles by door opening
 Percent over Entire Homogenous Area: <1% Known or Suspected Cause: Unknown
 Preventative Measures: wax floor

**AHERA REINSPECTION
ASSESSMENT FORM**

Inspector Signature: CJ Karoly Project Number: 241801

Accreditation ID Number: 059567 Inspection Date: 7/8/2024

Building: Boyertown Elementary School Homogenous Area: Floor tile

Sample Numbers: N/A Homogenous Area I.D. Number: N/A

Friable: No Total Quantity: 350 SF

ACBM by: N/A Result: N/A

Classify ACBM and suspected ACBM assumed to be ACM into one of the following categories:

Category	Type Of Material	Condition
<input type="checkbox"/> 1a.	Thermal System Insulation ACM	Damaged
<input type="checkbox"/> b.	Thermal system Insulation ACM	Significantly Damaged
<input type="checkbox"/> 2.	Friable ACM Surfacing Material	Damaged
<input type="checkbox"/> 3.	Friable ACM Surfacing Material	Significantly Damaged
<input type="checkbox"/> 4a.	Friable ACM Miscellaneous	Damaged
<input type="checkbox"/> b.	Friable ACM Miscellaneous	Significantly Damaged
<input type="checkbox"/> 5.	ACBM	Potential for Damage
<input type="checkbox"/> 6.	ACBM	Potential for Significant Damage
<input type="checkbox"/> 7.	Friable ACBM or Friable Suspected ACBM	Undamaged
<input checked="" type="checkbox"/> 8.	Non-Friable ACBM or Non-Friable Suspected ACM	

List General Functional Spaces e.g., Classrooms, Gym, Lunchroom

115

General Condition of Entire Homogenous Area: Good Accessibility: Limited

Potential For Disturbance: Limited Damage: 3 SF

Type of Damage: 3 loose tiles by heater

Percent over Entire Homogenous Area: <1% Known or Suspected Cause: Unknown

Preventative Measures: wax floor

**AHERA REINSPECTION
ASSESSMENT FORM**

Inspector Signature: CJ Karoly Project Number: 241801

Accreditation ID Number: 059567 Inspection Date: 7/8/2024

Building: Boyertown Elementary School Homogenous Area: Floor tile

Sample Numbers: N/A Homogenous Area I.D. Number: N/A

Friable: No Total Quantity: 3100 SF

ACBM by: N/A Result: N/A

Classify ACBM and suspected ACBM assumed to be ACM into one of the following categories:

Category	Type Of Material	Condition
<input type="checkbox"/>	1a. Thermal System Insulation ACM	Damaged
<input type="checkbox"/>	b. Thermal system Insulation ACM	Significantly Damaged
<input type="checkbox"/>	2. Friable ACM Surfacing Material	Damaged
<input type="checkbox"/>	3. Friable ACM Surfacing Material	Significantly Damaged
<input type="checkbox"/>	4a. Friable ACM Miscellaneous	Damaged
<input type="checkbox"/>	b. Friable ACM Miscellaneous	Significantly Damaged
<input type="checkbox"/>	5. ACM	Potential for Damage
<input type="checkbox"/>	6. ACM	Potential for Significant Damage
<input type="checkbox"/>	7. Friable ACBM or Friable Suspected ACBM	Undamaged
<input checked="" type="checkbox"/>	8. Non-Friable ACBM or Non-Friable Suspected ACM	

List General Functional Spaces e.g., Classrooms, Gym, Lunchroom

GYM

General Condition of Entire Homogenous Area: Good Accessibility: Limited

Potential For Disturbance: Limited Damage: 10 SF

Type of Damage: 10 broken tiles by door openings

Percent over Entire Homogenous Area: <1% Known or Suspected Cause: Unknown

Preventative Measures: _____

**AHERA REINSPECTION
ASSESSMENT FORM**

Inspector Signature: CJ Karoly Project Number: 241801

Accreditation ID Number: 059567 Inspection Date: 7/8/2024

Building: Boyertown Elementary School Homogenous Area: Floor tile

Sample Numbers: N/A Homogenous Area I.D. Number: N/A

Friable: No Total Quantity: 360 SF

ACBM by: N/A Result: N/A

Classify ACBM and suspected ACBM assumed to be ACM into one of the following categories:

Category	Type Of Material	Condition
<input type="checkbox"/>	1a. Thermal System Insulation ACM	Damaged
<input type="checkbox"/>	b. Thermal system Insulation ACM	Significantly Damaged
<input type="checkbox"/>	2. Friable ACM Surfacing Material	Damaged
<input type="checkbox"/>	3. Friable ACM Surfacing Material	Significantly Damaged
<input type="checkbox"/>	4a. Friable ACM Miscellaneous	Damaged
<input type="checkbox"/>	b. Friable ACM Miscellaneous	Significantly Damaged
<input type="checkbox"/>	5. ACM	Potential for Damage
<input type="checkbox"/>	6. ACM	Potential for Significant Damage
<input type="checkbox"/>	7. Friable ACBM or Friable Suspected ACBM	Undamaged
<input checked="" type="checkbox"/>	8. Non-Friable ACBM or Non-Friable Suspected ACM	

List General Functional Spaces e.g., Classrooms, Gym, Lunchroom

150

General Condition of Entire Homogenous Area: Good Accessibility: Limited

Potential For Disturbance: Limited Damage: 4 SF

Type of Damage: 4 broken tiles throughout

Percent over Entire Homogenous Area: 1% Known or Suspected Cause: Unknown

Preventative Measures: _____

**AHERA REINSPECTION
ASSESSMENT FORM**

Inspector Signature: CJ Karoly Project Number: 241801

Accreditation ID Number: 059567 Inspection Date: 7/8/2024

Building: Boyertown Elementary School Homogenous Area: Floor tile and Mastic

Sample Numbers: N/A Homogenous Area I.D. Number: N/A

Friable: No Total Quantity: 11,650 SF

ACBM by: N/A Result: N/A

Classify ACBM and suspected ACBM assumed to be ACM into one of the following categories:

Category	Type Of Material	Condition
<input type="checkbox"/>	1a. Thermal System Insulation ACM	Damaged
<input type="checkbox"/>	b. Thermal system Insulation ACM	Significantly Damaged
<input type="checkbox"/>	2. Friable ACM Surfacing Material	Damaged
<input type="checkbox"/>	3. Friable ACM Surfacing Material	Significantly Damaged
<input type="checkbox"/>	4a. Friable ACM Miscellaneous	Damaged
<input type="checkbox"/>	b. Friable ACM Miscellaneous	Significantly Damaged
<input type="checkbox"/>	5. ACM	Potential for Damage
<input type="checkbox"/>	6. ACM	Potential for Significant Damage
<input type="checkbox"/>	7. Friable ACBM or Friable Suspected ACBM	Undamaged
<input checked="" type="checkbox"/>	8. Non-Friable ACBM or Non-Friable Suspected ACM	

List General Functional Spaces e.g., Classrooms, Gym, Lunchroom

Multi-purpose room, Gymnasium, Gymnasium office, Stage, Storage 242, Storage 245, Room 224, Room 173 IT, Room 173 ESL

Storage 147, Storage 149, Storage 150, Room 114 Library Office, Room 115, Storage 122

Storage Rooms between 118 and 121, Storage Rooms between 177 and 182

General Condition of Entire Homogenous Area: Good Accessibility: Limited

Potential For Disturbance: Limited Damage: N/A

Type of Damage: N/A

Percent over Entire Homogenous Area: N/A Known or Suspected Cause: N/A

Preventative Measures: N/A

**AHERA REINSPECTION
ASSESSMENT FORM**

Inspector Signature: CJ Karoly Project Number: 241801

Accreditation ID Number: 059567 Inspection Date: 7/8/2024

Building: Boyertown Elementary School Homogenous Area: HVAC Cloth Expansion joint

Sample Numbers: N/A Homogenous Area I.D. Number: N/A

Friable: No Total Quantity: 2 EA

ACBM by: N/A Result: N/A

Classify ACBM and suspected ACBM assumed to be ACM into one of the following categories:

Category	Type Of Material	Condition
<input type="checkbox"/>	1a. Thermal System Insulation ACM	Damaged
<input type="checkbox"/>	b. Thermal system Insulation ACM	Significantly Damaged
<input type="checkbox"/>	2. Friable ACM Surfacing Material	Damaged
<input type="checkbox"/>	3. Friable ACM Surfacing Material	Significantly Damaged
<input type="checkbox"/>	4a. Friable ACM Miscellaneous	Damaged
<input type="checkbox"/>	b. Friable ACM Miscellaneous	Significantly Damaged
<input type="checkbox"/>	5. ACM	Potential for Damage
<input type="checkbox"/>	6. ACM	Potential for Significant Damage
<input type="checkbox"/>	7. Friable ACBM or Friable Suspected ACBM	Undamaged
<input checked="" type="checkbox"/>	8. Non-Friable ACBM or Non-Friable Suspected ACM	

List General Functional Spaces e.g., Classrooms, Gym, Lunchroom

Mechanical Room 222

General Condition of Entire Homogenous Area: Good Accessibility: Limited

Potential For Disturbance: Limited Damage: N/A

Type of Damage: N/A

Percent over Entire Homogenous Area: N/A Known or Suspected Cause: N/A

Preventative Measures: N/A

**AHERA REINSPECTION
ASSESSMENT FORM**

Inspector Signature: CJ Karoly Project Number: 241801

Accreditation ID Number: 059567 Inspection Date: 7/8/2024

Building: Boyertown Elementary School Homogenous Area: Blackboard adhesive

Sample Numbers: N/A Homogenous Area I.D. Number: N/A

Friable: No Total Quantity: 100 SF

ACBM by: N/A Result: N/A

Classify ACBM and suspected ACBM assumed to be ACM into one of the following categories:

Category	Type Of Material	Condition
<input type="checkbox"/>	1a. Thermal System Insulation ACM	Damaged
<input type="checkbox"/>	b. Thermal system Insulation ACM	Significantly Damaged
<input type="checkbox"/>	2. Friable ACM Surfacing Material	Damaged
<input type="checkbox"/>	3. Friable ACM Surfacing Material	Significantly Damaged
<input type="checkbox"/>	4a. Friable ACM Miscellaneous	Damaged
<input type="checkbox"/>	b. Friable ACM Miscellaneous	Significantly Damaged
<input type="checkbox"/>	5. ACM	Potential for Damage
<input type="checkbox"/>	6. ACM	Potential for Significant Damage
<input type="checkbox"/>	7. Friable ACBM or Friable Suspected ACBM	Undamaged
<input checked="" type="checkbox"/>	8. Non-Friable ACBM or Non-Friable Suspected ACM	

List General Functional Spaces e.g., Classrooms, Gym, Lunchroom

104, 105, 106, 107, 108, 115, 118, 121, 122, 125, 126, 127, 128, 143, 144, 145, 146
147, 155, 156, 157, 158, 173, 177, 182, 183, 184, 185, 186, 187, 188, 196, 197, 199, 201, 203, 205

General Condition of Entire Homogenous Area: Good Accessibility: Limited

Potential For Disturbance: Limited Damage: N/A

Type of Damage: N/A

Percent over Entire Homogenous Area: N/A Known or Suspected Cause: N/A

Preventative Measures: N/A

**AHERA REINSPECTION
ASSESSMENT FORM**

Inspector Signature: CJ Karoly Project Number: 241801
 Accreditation ID Number: 059567 Inspection Date: 7/8/2024
 Building: Boyertown High School Homogenous Area: Fire Doors
 Sample Numbers: N/A Homogenous Area I.D. Number: N/A
 Friable: Yes Total Quantity: 4 EA
 ACBM by: N/A Result: N/A

Classify ACBM and suspected ACBM assumed to be ACM into one of the following categories:

Category	Type Of Material	Condition
<input type="checkbox"/>	1a. Thermal System Insulation ACM	Damaged
<input type="checkbox"/>	b. Thermal system Insulation ACM	Significantly Damaged
<input type="checkbox"/>	2. Friable ACM Surfacing Material	Damaged
<input type="checkbox"/>	3. Friable ACM Surfacing Material	Significantly Damaged
<input type="checkbox"/>	4a. Friable ACM Miscellaneous	Damaged
<input type="checkbox"/>	b. Friable ACM Miscellaneous	Significantly Damaged
<input type="checkbox"/>	5. ACBM	Potential for Damage
<input type="checkbox"/>	6. ACBM	Potential for Significant Damage
<input checked="" type="checkbox"/>	7. Friable ACBM or Friable Suspected ACBM	Undamaged
<input type="checkbox"/>	8. Non-Friable ACBM or Non-Friable Suspected ACM	

List General Functional Spaces e.g., Classrooms, Gym, Lunchroom

Stairwell #1, 2nd floor, Stairwell #1, 3rd floor

General Condition of Entire Homogenous Area: Good Accessibility: Limited
 Potential For Disturbance: Limited Damage: N/A
 Type of Damage: N/A
 Percent over Entire Homogenous Area: N/A Known or Suspected Cause: N/A
 Preventative Measures: N/A

**AHERA REINSPECTION
ASSESSMENT FORM**

Inspector Signature: CJ Karoly Project Number: 241801
 Accreditation ID Number: 059567 Inspection Date: 7/10/2024
 Building: Boyertown middle school East Homogenous Area: Acoustical Ceiling Plaster
 Sample Numbers: N/A Homogenous Area I.D. Number: N/A
 Friable: Yes Total Quantity: 7300 SF
 ACBM by: N/A Result: N/A

Classify ACBM and suspected ACBM assumed to be ACM into one of the following categories:

Category	Type Of Material	Condition
<input type="checkbox"/>	1a. Thermal System Insulation ACM	Damaged
<input type="checkbox"/>	b. Thermal system Insulation ACM	Significantly Damaged
<input type="checkbox"/>	2. Friable ACM Surfacing Material	Damaged
<input type="checkbox"/>	3. Friable ACM Surfacing Material	Significantly Damaged
<input type="checkbox"/>	4a. Friable ACM Miscellaneous	Damaged
<input type="checkbox"/>	b. Friable ACM Miscellaneous	Significantly Damaged
<input type="checkbox"/>	5. ACM	Potential for Damage
<input type="checkbox"/>	6. ACM	Potential for Significant Damage
<input checked="" type="checkbox"/>	7. Friable ACBM or Friable Suspected ACBM	Undamaged
<input type="checkbox"/>	8. Non-Friable ACBM or Non-Friable Suspected ACM	

List General Functional Spaces e.g., Classrooms, Gym, Lunchroom

Planetarium

General Condition of Entire Homogenous Area: Good Accessibility: Limited
 Potential For Disturbance: Limited Damage: N/A
 Type of Damage: N/A
 Percent over Entire Homogenous Area: N/A Known or Suspected Cause: N/A
 Preventative Measures: N/A

**AHERA REINSPECTION
ASSESSMENT FORM**

Inspector Signature: CJ Karoly Project Number: 241801
 Accreditation ID Number: 059567 Inspection Date: 7/10/2024
 Building: Boyertown middle school East Homogenous Area: Fire Doors
 Sample Numbers: N/A Homogenous Area I.D. Number: N/A
 Friable: Yes Total Quantity: 12 EA
 ACBM by: N/A Result: N/A

Classify ACBM and suspected ACBM assumed to be ACM into one of the following categories:

Category	Type Of Material	Condition
<input type="checkbox"/>	1a. Thermal System Insulation ACM	Damaged
<input type="checkbox"/>	b. Thermal system Insulation ACM	Significantly Damaged
<input type="checkbox"/>	2. Friable ACM Surfacing Material	Damaged
<input type="checkbox"/>	3. Friable ACM Surfacing Material	Significantly Damaged
<input type="checkbox"/>	4a. Friable ACM Miscellaneous	Damaged
<input type="checkbox"/>	b. Friable ACM Miscellaneous	Significantly Damaged
<input type="checkbox"/>	5. ACM	Potential for Damage
<input type="checkbox"/>	6. ACM	Potential for Significant Damage
<input checked="" type="checkbox"/>	7. Friable ACBM or Friable Suspected ACBM	Undamaged
<input type="checkbox"/>	8. Non-Friable ACBM or Non-Friable Suspected ACM	

List General Functional Spaces e.g., Classrooms, Gym, Lunchroom

Boiler Room, Mechanical Room, 522- loading dock, 520, 516 - storage, 517 - storage

General Condition of Entire Homogenous Area: Good Accessibility: Limited
 Potential For Disturbance: Limited Damage: N/A
 Type of Damage: N/A
 Percent over Entire Homogenous Area: N/A Known or Suspected Cause: N/A
 Preventative Measures: N/A

**AHERA REINSPECTION
ASSESSMENT FORM**

Inspector Signature: CJ Karoly Project Number: 241801

Accreditation ID Number: 059567 Inspection Date: 7/11/2024

Building: Boyertown middle school West Homogenous Area: Fire Doors

Sample Numbers: N/A Homogenous Area I.D. Number: N/A

Friable: Yes Total Quantity: 6 EA

ACBM by: N/A Result: N/A

Classify ACBM and suspected ACBM assumed to be ACM into one of the following categories:

Category	Type Of Material	Condition
<input type="checkbox"/> 1a.	Thermal System Insulation ACM	Damaged
<input type="checkbox"/> b.	Thermal system Insulation ACM	Significantly Damaged
<input type="checkbox"/> 2.	Friable ACM Surfacing Material	Damaged
<input type="checkbox"/> 3.	Friable ACM Surfacing Material	Significantly Damaged
<input type="checkbox"/> 4a.	Friable ACM Miscellaneous	Damaged
<input type="checkbox"/> b.	Friable ACM Miscellaneous	Significantly Damaged
<input type="checkbox"/> 5.	ACBM	Potential for Damage
<input type="checkbox"/> 6.	ACBM	Potential for Significant Damage
<input checked="" type="checkbox"/> 7.	Friable ACBM or Friable Suspected ACBM	Undamaged
<input type="checkbox"/> 8.	Non-Friable ACBM or Non-Friable Suspected ACM	

List General Functional Spaces e.g., Classrooms, Gym, Lunchroom

Loadng Dock, Boiler Room

General Condition of Entire Homogenous Area: Good Accessibility: Limited

Potential For Disturbance: Limited Damage: N/A

Type of Damage: N/A

Percent over Entire Homogenous Area: N/A Known or Suspected Cause: N/A

Preventative Measures: N/A

**AHERA REINSPECTION
ASSESSMENT FORM**

Inspector Signature: CJ Karoly Project Number: 241801
 Accreditation ID Number: 059567 Inspection Date: 7/11/2024
 Building: Boyertown middle school West Homogenous Area: Blackboard Adhesive
 Sample Numbers: N/A Homogenous Area I.D. Number: N/A
 Friable: No Total Quantity: 73 EA
 ACBM by: N/A Result: N/A

Classify ACBM and suspected ACBM assumed to be ACM into one of the following categories:

Category	Type Of Material	Condition
<input type="checkbox"/>	1a. Thermal System Insulation ACM	Damaged
<input type="checkbox"/>	b. Thermal system Insulation ACM	Significantly Damaged
<input type="checkbox"/>	2. Friable ACM Surfacing Material	Damaged
<input type="checkbox"/>	3. Friable ACM Surfacing Material	Significantly Damaged
<input type="checkbox"/>	4a. Friable ACM Miscellaneous	Damaged
<input type="checkbox"/>	b. Friable ACM Miscellaneous	Significantly Damaged
<input type="checkbox"/>	5. ACBM	Potential for Damage
<input type="checkbox"/>	6. ACBM	Potential for Significant Damage
<input type="checkbox"/>	7. Friable ACBM or Friable Suspected ACBM	Undamaged
<input checked="" type="checkbox"/>	8. Non-Friable ACBM or Non-Friable Suspected ACM	

List General Functional Spaces e.g., Classrooms, Gym, Lunchroom

19, 20, 21, 23, 24, 25, 26, 27, 28, 29, 32, 33, 34, 35, 36, 37, 38, 39, 40, 42, 43, 44, 45, 46, 47, 47.1, 48
61, 62, 63, 64, 70, Band Room

General Condition of Entire Homogenous Area: Good Accessibility: Limited
 Potential For Disturbance: Limited Damage: N/A
 Type of Damage: N/A
 Percent over Entire Homogenous Area: N/A Known or Suspected Cause: N/A
 Preventative Measures: N/A

AHERA REINSPECTION
ASSESSMENT FORM

Inspector Signature: CJ Karoly Project Number: 241801

Accreditation ID Number: 059567 Inspection Date: 7/8/2024

Building: Colebrookdale Elementary School Homogenous Area: Blackboard Adhesive

Sample Numbers: N/A Homogenous Area I.D. Number: N/A

Friable: No Total Quantity: 24 SF

ACBM by: N/A Result: N/A

Classify ACBM and suspected ACBM assumed to be ACM into one of the following categories:

Category	Type Of Material	Condition
<input type="checkbox"/> 1a.	Thermal System Insulation ACM	Damaged
<input type="checkbox"/> b.	Thermal system Insulation ACM	Significantly Damaged
<input type="checkbox"/> 2.	Friable ACM Surfacing Material	Damaged
<input type="checkbox"/> 3.	Friable ACM Surfacing Material	Significantly Damaged
<input type="checkbox"/> 4a.	Friable ACM Miscellaneous	Damaged
<input type="checkbox"/> b.	Friable ACM Miscellaneous	Significantly Damaged
<input type="checkbox"/> 5.	ACBM	Potential for Damage
<input type="checkbox"/> 6.	ACBM	Potential for Significant Damage
<input type="checkbox"/> 7.	Friable ACBM or Friable Suspected ACBM	Undamaged
<input checked="" type="checkbox"/> 8.	Non-Friable ACBM or Non-Friable Suspected ACM	

List General Functional Spaces e.g., Classrooms, Gym, Lunchroom

101, 102, 103 Art-room, Hallway outside Library, 100, 201, 202, 203, 204, 205, 206, 207, 208

210, 211, 212, 301, 302, 303, 304, Guidance office, Conference room

General Condition of Entire Homogenous Area: Good Accessibility: Limited

Potential For Disturbance: Limited Damage: N/A

Type of Damage: N/A

Percent over Entire Homogenous Area: N/A Known or Suspected Cause: N/A

Preventative Measures: N/A

AHERA REINSPECTION
ASSESSMENT FORM

Inspector Signature: CJ Karoly Project Number: 241801
 Accreditation ID Number: 059567 Inspection Date: 7/8/2024
 Building: Colebrookdale Elementary School Homogenous Area: Transite Skylights
 Sample Numbers: N/A Homogenous Area I.D. Number: N/A
 Friable: No Total Quantity: 28 SF
 ACBM by: N/A Result: N/A

Classify ACBM and suspected ACBM assumed to be ACM into one of the following categories:

Category	Type Of Material	Condition
<input type="checkbox"/> 1a.	Thermal System Insulation ACM	Damaged
<input type="checkbox"/> b.	Thermal system Insulation ACM	Significantly Damaged
<input type="checkbox"/> 2.	Friable ACM Surfacing Material	Damaged
<input type="checkbox"/> 3.	Friable ACM Surfacing Material	Significantly Damaged
<input type="checkbox"/> 4a.	Friable ACM Miscellaneous	Damaged
<input type="checkbox"/> b.	Friable ACM Miscellaneous	Significantly Damaged
<input type="checkbox"/> 5.	ACBM	Potential for Damage
<input type="checkbox"/> 6.	ACBM	Potential for Significant Damage
<input type="checkbox"/> 7.	Friable ACBM or Friable Suspected ACBM	Undamaged
<input checked="" type="checkbox"/> 8.	Non-Friable ACBM or Non-Friable Suspected ACM	

List General Functional Spaces e.g., Classrooms, Gym, Lunchroom

Corridor Outside Library

General Condition of Entire Homogenous Area: Good Accessibility: Limited
 Potential For Disturbance: Limited Damage: N/A
 Type of Damage: N/A
 Percent over Entire Homogenous Area: N/A Known or Suspected Cause: N/A
 Preventative Measures: N/A

**AHERA REINSPECTION
ASSESSMENT FORM**

Inspector Signature: CJ Karoly Project Number: 241801

Accreditation ID Number: 059567 Inspection Date: 7/8/2024

Building: Colebrookdale Elementary School Homogenous Area: Transite Panels

Sample Numbers: N/A Homogenous Area I.D. Number: N/A

Friable: No Total Quantity: Unknown

ACBM by: N/A Result: N/A

Classify ACBM and suspected ACBM assumed to be ACM into one of the following categories:

Category	Type Of Material	Condition
<input type="checkbox"/> 1a.	Thermal System Insulation ACM	Damaged
<input type="checkbox"/> b.	Thermal system Insulation ACM	Significantly Damaged
<input type="checkbox"/> 2.	Friable ACM Surfacing Material	Damaged
<input type="checkbox"/> 3.	Friable ACM Surfacing Material	Significantly Damaged
<input type="checkbox"/> 4a.	Friable ACM Miscellaneous	Damaged
<input type="checkbox"/> b.	Friable ACM Miscellaneous	Significantly Damaged
<input type="checkbox"/> 5.	ACBM	Potential for Damage
<input type="checkbox"/> 6.	ACBM	Potential for Significant Damage
<input type="checkbox"/> 7.	Friable ACBM or Friable Suspected ACBM	Undamaged
<input checked="" type="checkbox"/> 8.	Non-Friable ACBM or Non-Friable Suspected ACM	

List General Functional Spaces e.g., Classrooms, Gym, Lunchroom

Multi Purpose Room

General Condition of Entire Homogenous Area: Good Accessibility: Limited

Potential For Disturbance: Limited Damage: N/A

Type of Damage: N/A

Percent over Entire Homogenous Area: N/A Known or Suspected Cause: N/A

Preventative Measures: N/A

**AHERA REINSPECTION
ASSESSMENT FORM**

Inspector Signature: CJ Karoly Project Number: 241801
 Accreditation ID Number: 059567 Inspection Date: 7/8/2024
 Building: Colebrookdale Elementary School Homogenous Area: Transite Window Sills
 Sample Numbers: N/A Homogenous Area I.D. Number: N/A
 Friable: No Total Quantity: Unknown
 ACBM by: N/A Result: N/A

Classify ACBM and suspected ACBM assumed to be ACM into one of the following categories:

Category	Type Of Material	Condition
<input type="checkbox"/> 1a.	Thermal System Insulation ACM	Damaged
<input type="checkbox"/> b.	Thermal system Insulation ACM	Significantly Damaged
<input type="checkbox"/> 2.	Friable ACM Surfacing Material	Damaged
<input type="checkbox"/> 3.	Friable ACM Surfacing Material	Significantly Damaged
<input type="checkbox"/> 4a.	Friable ACM Miscellaneous	Damaged
<input type="checkbox"/> b.	Friable ACM Miscellaneous	Significantly Damaged
<input type="checkbox"/> 5.	ACBM	Potential for Damage
<input type="checkbox"/> 6.	ACBM	Potential for Significant Damage
<input type="checkbox"/> 7.	Friable ACBM or Friable Suspected ACBM	Undamaged
<input checked="" type="checkbox"/> 8.	Non-Friable ACBM or Non-Friable Suspected ACM	

List General Functional Spaces e.g., Classrooms, Gym, Lunchroom

Throughout

General Condition of Entire Homogenous Area: Good Accessibility: Limited
 Potential For Disturbance: Limited Damage: N/A
 Type of Damage: N/A
 Percent over Entire Homogenous Area: N/A Known or Suspected Cause: N/A
 Preventative Measures: N/A

AHERA REINSPECTION
ASSESSMENT FORM

Inspector Signature: CJ Karoly Project Number: 241801
 Accreditation ID Number: 059567 Inspection Date: 7/8/2024
 Building: Colebrookdale Elementary School Homogenous Area: Fire Doors
 Sample Numbers: N/A Homogenous Area I.D. Number: N/A
 Friable: Yes Total Quantity: 4 EA
 ACBM by: N/A Result: N/A

Classify ACBM and suspected ACBM assumed to be ACM into one of the following categories:

Category	Type Of Material	Condition
<input type="checkbox"/> 1a.	Thermal System Insulation ACM	Damaged
<input type="checkbox"/> b.	Thermal system Insulation ACM	Significantly Damaged
<input type="checkbox"/> 2.	Friable ACM Surfacing Material	Damaged
<input type="checkbox"/> 3.	Friable ACM Surfacing Material	Significantly Damaged
<input type="checkbox"/> 4a.	Friable ACM Miscellaneous	Damaged
<input type="checkbox"/> b.	Friable ACM Miscellaneous	Significantly Damaged
<input type="checkbox"/> 5.	ACBM	Potential for Damage
<input type="checkbox"/> 6.	ACBM	Potential for Significant Damage
<input checked="" type="checkbox"/> 7.	Friable ACBM or Friable Suspected ACBM	Undamaged
<input type="checkbox"/> 8.	Non-Friable ACBM or Non-Friable Suspected ACM	

List General Functional Spaces e.g., Classrooms, Gym, Lunchroom

Boiler Room, Maintenance Room

General Condition of Entire Homogenous Area: Good Accessibility: Limited
 Potential For Disturbance: Limited Damage: N/A
 Type of Damage: N/A
 Percent over Entire Homogenous Area: N/A Known or Suspected Cause: N/A
 Preventative Measures: N/A

**AHERA REINSPECTION
ASSESSMENT FORM**

Inspector Signature: CJ Karoly Project Number: 241801

Accreditation ID Number: 059567 Inspection Date: 7/9/2024

Building: Earl Elementary School Homogenous Area: Plaster Ceiling

Sample Numbers: N/A Homogenous Area I.D. Number: N/A

Friable: No Total Quantity: 675 SF

ACBM by: N/A Result: N/A

Classify ACBM and suspected ACBM assumed to be ACM into one of the following categories:

Category	Type Of Material	Condition
<input type="checkbox"/> 1a.	Thermal System Insulation ACM	Damaged
<input type="checkbox"/> b.	Thermal system Insulation ACM	Significantly Damaged
<input type="checkbox"/> 2.	Friable ACM Surfacing Material	Damaged
<input type="checkbox"/> 3.	Friable ACM Surfacing Material	Significantly Damaged
<input checked="" type="checkbox"/> 4a.	Friable ACM Miscellaneous	Damaged
<input type="checkbox"/> b.	Friable ACM Miscellaneous	Significantly Damaged
<input type="checkbox"/> 5.	ACBM	Potential for Damage
<input type="checkbox"/> 6.	ACBM	Potential for Significant Damage
<input type="checkbox"/> 7.	Friable ACBM or Friable Suspected ACBM	Undamaged
<input type="checkbox"/> 8.	Non-Friable ACBM or Non-Friable Suspected ACM	

List General Functional Spaces e.g., Classrooms, Gym, Lunchroom

Boiler Room

General Condition of Entire Homogenous Area: Good Accessibility: Limited

Potential For Disturbance: Limited Damage: 6 SF

Type of Damage: Plaster ceiling cracking above water heater

Percent over Entire Homogenous Area: <1% Known or Suspected Cause: Unknown

Preventative Measures: N/A

AHERA REINSPECTION
ASSESSMENT FORM

Inspector Signature: CJ Karoly Project Number: 241801

Accreditation ID Number: 059567 Inspection Date: 7/15/2024

Building: Education Center Homogenous Area: Fire Doors

Sample Numbers: N/A Homogenous Area I.D. Number: N/A

Friable: Yes Total Quantity: 2 EA

ACBM by: N/A Result: N/A

Classify ACBM and suspected ACBM assumed to be ACM into one of the following categories:

Category	Type Of Material	Condition
<input type="checkbox"/> 1a.	Thermal System Insulation ACM	Damaged
<input type="checkbox"/> b.	Thermal system Insulation ACM	Significantly Damaged
<input type="checkbox"/> 2.	Friable ACM Surfacing Material	Damaged
<input type="checkbox"/> 3.	Friable ACM Surfacing Material	Significantly Damaged
<input type="checkbox"/> 4a.	Friable ACM Miscellaneous	Damaged
<input type="checkbox"/> b.	Friable ACM Miscellaneous	Significantly Damaged
<input type="checkbox"/> 5.	ACBM	Potential for Damage
<input type="checkbox"/> 6.	ACBM	Potential for Significant Damage
<input checked="" type="checkbox"/> 7.	Friable ACBM or Friable Suspected ACBM	Undamaged
<input type="checkbox"/> 8.	Non-Friable ACBM or Non-Friable Suspected ACM	

List General Functional Spaces e.g., Classrooms, Gym, Lunchroom

Boiler Room, Vault

General Condition of Entire Homogenous Area: Good Accessibility: Limited

Potential For Disturbance: Limited Damage: N/A

Type of Damage: N/A

Percent over Entire Homogenous Area: N/A Known or Suspected Cause: Unknown

Preventative Measures: N/A

**AHERA REINSPECTION
ASSESSMENT FORM**

Inspector Signature: CJ Karoly Project Number: 241801
 Accreditation ID Number: 059567 Inspection Date: 7/15/2024
 Building: Education Center Homogenous Area: Floor Tile
 Sample Numbers: N/A Homogenous Area I.D. Number: N/A
 Friable: No Total Quantity: 125 SF
 ACBM by: N/A Result: N/A

Classify ACBM and suspected ACBM assumed to be ACM into one of the following categories:

Category	Type Of Material	Condition
<input type="checkbox"/> 1a.	Thermal System Insulation ACM	Damaged
<input type="checkbox"/> b.	Thermal system Insulation ACM	Significantly Damaged
<input type="checkbox"/> 2.	Friable ACM Surfacing Material	Damaged
<input type="checkbox"/> 3.	Friable ACM Surfacing Material	Significantly Damaged
<input type="checkbox"/> 4a.	Friable ACM Miscellaneous	Damaged
<input type="checkbox"/> b.	Friable ACM Miscellaneous	Significantly Damaged
<input type="checkbox"/> 5.	ACBM	Potential for Damage
<input type="checkbox"/> 6.	ACBM	Potential for Significant Damage
<input type="checkbox"/> 7.	Friable ACBM or Friable Suspected ACBM	Undamaged
<input checked="" type="checkbox"/> 8.	Non-Friable ACBM or Non-Friable Suspected ACM	

List General Functional Spaces e.g., Classrooms, Gym, Lunchroom

Vault Room

General Condition of Entire Homogenous Area: Good Accessibility: Limited
 Potential For Disturbance: Limited Damage: 3 SF
 Type of Damage: 3 cracked floor tile by door
 Percent over Entire Homogenous Area: 1% Known or Suspected Cause: Unknown
 Preventative Measures: wax floors

AHERA REINSPECTION
ASSESSMENT FORM

Inspector Signature: CJ Karoly Project Number: 241801

Accreditation ID Number: 059567 Inspection Date: 7/15/2024

Building: Education Center Homogenous Area: Floor Tile and Mastic

Sample Numbers: N/A Homogenous Area I.D. Number: N/A

Friable: No Total Quantity: 385 SF

ACBM by: N/A Result: N/A

Classify ACBM and suspected ACBM assumed to be ACM into one of the following categories:

Category	Type Of Material	Condition
<input type="checkbox"/> 1a.	Thermal System Insulation ACM	Damaged
<input type="checkbox"/> b.	Thermal system Insulation ACM	Significantly Damaged
<input type="checkbox"/> 2.	Friable ACM Surfacing Material	Damaged
<input type="checkbox"/> 3.	Friable ACM Surfacing Material	Significantly Damaged
<input type="checkbox"/> 4a.	Friable ACM Miscellaneous	Damaged
<input type="checkbox"/> b.	Friable ACM Miscellaneous	Significantly Damaged
<input type="checkbox"/> 5.	ACBM	Potential for Damage
<input type="checkbox"/> 6.	ACBM	Potential for Significant Damage
<input type="checkbox"/> 7.	Friable ACBM or Friable Suspected ACBM	Undamaged
<input checked="" type="checkbox"/> 8.	Non-Friable ACBM or Non-Friable Suspected ACM	

List General Functional Spaces e.g., Classrooms, Gym, Lunchroom

Old Mail Room, Data Processing, Lunch Room

General Condition of Entire Homogenous Area: Good Accessibility: Limited

Potential For Disturbance: Limited Damage: N/A

Type of Damage: N/A

Percent over Entire Homogenous Area: N/A Known or Suspected Cause: N/A

Preventative Measures: N/A

**AHERA REINSPECTION
ASSESSMENT FORM**

Inspector Signature: CJ Karoly Project Number: 241801
 Accreditation ID Number: 059567 Inspection Date: 7/9/2024
 Building: Gilbertsville Elementary School Homogenous Area: Blackboard Adhesive
 Sample Numbers: N/A Homogenous Area I.D. Number: N/A
 Friable: No Total Quantity: 110 Ea
 ACBM by: N/A Result: N/A

Classify ACBM and suspected ACBM assumed to be ACM into one of the following categories:

Category	Type Of Material	Condition
<input type="checkbox"/> 1a.	Thermal System Insulation ACM	Damaged
<input type="checkbox"/> b.	Thermal system Insulation ACM	Significantly Damaged
<input type="checkbox"/> 2.	Friable ACM Surfacing Material	Damaged
<input type="checkbox"/> 3.	Friable ACM Surfacing Material	Significantly Damaged
<input type="checkbox"/> 4a.	Friable ACM Miscellaneous	Damaged
<input type="checkbox"/> b.	Friable ACM Miscellaneous	Significantly Damaged
<input type="checkbox"/> 5.	ACBM	Potential for Damage
<input type="checkbox"/> 6.	ACBM	Potential for Significant Damage
<input type="checkbox"/> 7.	Friable ACBM or Friable Suspected ACBM	Undamaged
<input checked="" type="checkbox"/> 8.	Non-Friable ACBM or Non-Friable Suspected ACM	

List General Functional Spaces e.g., Classrooms, Gym, Lunchroom

111, 112, 113, 114, SGI room, 121, 122, 123, 124, Reading Room - Room 26, Faculty Lounge, 124, 28
30, 31, Reading room adj. to Rm 30, 131, 132, 133, 134, 135, 136 computer room, 130, 137-D, 141, 142, faculty dining
143, 144, Kindergarten 1, Kindergarten 2, 151, 152, 153, 154, 161, 162, 163, 164, library, music room, instrumental music

General Condition of Entire Homogenous Area: Good Accessibility: Limited
 Potential For Disturbance: Limited Damage: N/A
 Type of Damage: N/A
 Percent over Entire Homogenous Area: N/A Known or Suspected Cause: N/A
 Preventative Measures: N/A

**AHERA REINSPECTION
ASSESSMENT FORM**

Inspector Signature: CJ Karoly Project Number: 241801

Accreditation ID Number: 059567 Inspection Date: 7/9/2024

Building: Gilbertsville Elementary School Homogenous Area: Cloth HVAC Expansion Joint

Sample Numbers: N/A Homogenous Area I.D. Number: N/A

Friable: No Total Quantity: 1 EA

ACBM by: N/A Result: N/A

Classify ACBM and suspected ACBM assumed to be ACM into one of the following categories:

Category	Type Of Material	Condition
<input type="checkbox"/> 1a.	Thermal System Insulation ACM	Damaged
<input type="checkbox"/> b.	Thermal system Insulation ACM	Significantly Damaged
<input type="checkbox"/> 2.	Friable ACM Surfacing Material	Damaged
<input type="checkbox"/> 3.	Friable ACM Surfacing Material	Significantly Damaged
<input type="checkbox"/> 4a.	Friable ACM Miscellaneous	Damaged
<input type="checkbox"/> b.	Friable ACM Miscellaneous	Significantly Damaged
<input type="checkbox"/> 5.	ACBM	Potential for Damage
<input type="checkbox"/> 6.	ACBM	Potential for Significant Damage
<input type="checkbox"/> 7.	Friable ACBM or Friable Suspected ACBM	Undamaged
<input checked="" type="checkbox"/> 8.	Non-Friable ACBM or Non-Friable Suspected ACM	

List General Functional Spaces e.g., Classrooms, Gym, Lunchroom

Boiler Room

General Condition of Entire Homogenous Area: Good Accessibility: Limited

Potential For Disturbance: Limited Damage: N/A

Type of Damage: N/A

Percent over Entire Homogenous Area: N/A Known or Suspected Cause: N/A

Preventative Measures: N/A

**AHERA REINSPECTION
ASSESSMENT FORM**

Inspector Signature: CJ Karoly Project Number: 241801

Accreditation ID Number: 059567 Inspection Date: 7/9/2024

Building: Gilbertsville Elementary School Homogenous Area: Floor tile and Mastic

Sample Numbers: N/A Homogenous Area I.D. Number: N/A

Friable: No Total Quantity: Unknown

ACBM by: N/A Result: N/A

Classify ACBM and suspected ACBM assumed to be ACM into one of the following categories:

Category	Type Of Material	Condition
<input type="checkbox"/> 1a.	Thermal System Insulation ACM	Damaged
<input type="checkbox"/> b.	Thermal system Insulation ACM	Significantly Damaged
<input type="checkbox"/> 2.	Friable ACM Surfacing Material	Damaged
<input type="checkbox"/> 3.	Friable ACM Surfacing Material	Significantly Damaged
<input type="checkbox"/> 4a.	Friable ACM Miscellaneous	Damaged
<input type="checkbox"/> b.	Friable ACM Miscellaneous	Significantly Damaged
<input type="checkbox"/> 5.	ACBM	Potential for Damage
<input type="checkbox"/> 6.	ACBM	Potential for Significant Damage
<input type="checkbox"/> 7.	Friable ACBM or Friable Suspected ACBM	Undamaged
<input checked="" type="checkbox"/> 8.	Non-Friable ACBM or Non-Friable Suspected ACM	

List General Functional Spaces e.g., Classrooms, Gym, Lunchroom

Under walls

General Condition of Entire Homogenous Area: Good Accessibility: Limited

Potential For Disturbance: Limited Damage: N/A

Type of Damage: N/A

Percent over Entire Homogenous Area: N/A Known or Suspected Cause: N/A

Preventative Measures: N/A

**AHERA REINSPECTION
ASSESSMENT FORM**

Inspector Signature: CJ Karoly Project Number: 241801
 Accreditation ID Number: 059567 Inspection Date: 7/9/2024
 Building: Gilbertsville Elementary School Homogenous Area: Fire Doors
 Sample Numbers: N/A Homogenous Area I.D. Number: N/A
 Friable: Yes Total Quantity: 7 Ea
 ACBM by: N/A Result: N/A

Classify ACBM and suspected ACBM assumed to be ACM into one of the following categories:

Category	Type Of Material	Condition
<input type="checkbox"/> 1a.	Thermal System Insulation ACM	Damaged
<input type="checkbox"/> b.	Thermal system Insulation ACM	Significantly Damaged
<input type="checkbox"/> 2.	Friable ACM Surfacing Material	Damaged
<input type="checkbox"/> 3.	Friable ACM Surfacing Material	Significantly Damaged
<input type="checkbox"/> 4a.	Friable ACM Miscellaneous	Damaged
<input type="checkbox"/> b.	Friable ACM Miscellaneous	Significantly Damaged
<input type="checkbox"/> 5.	ACBM	Potential for Damage
<input type="checkbox"/> 6.	ACBM	Potential for Significant Damage
<input checked="" type="checkbox"/> 7.	Friable ACBM or Friable Suspected ACBM	Undamaged
<input type="checkbox"/> 8.	Non-Friable ACBM or Non-Friable Suspected ACM	

List General Functional Spaces e.g., Classrooms, Gym, Lunchroom

Boiler Room, Room outside boiler room, music room corridors, basement rooms

General Condition of Entire Homogenous Area: Good Accessibility: Limited
 Potential For Disturbance: Limited Damage: N/A
 Type of Damage: N/A
 Percent over Entire Homogenous Area: N/A Known or Suspected Cause: N/A
 Preventative Measures: N/A

AHERA REINSPECTION
ASSESSMENT FORM

Inspector Signature: CJ Karoly Project Number: 241801
 Accreditation ID Number: 059567 Inspection Date: 7/9/2024
 Building: Gilbertsville Elementary School Homogenous Area: Glue Dots
 Sample Numbers: N/A Homogenous Area I.D. Number: N/A
 Friable: No Total Quantity: 16 SF
 ACBM by: N/A Result: N/A

Classify ACBM and suspected ACBM assumed to be ACM into one of the following categories:

Category	Type Of Material	Condition
<input type="checkbox"/> 1a.	Thermal System Insulation ACM	Damaged
<input type="checkbox"/> b.	Thermal system Insulation ACM	Significantly Damaged
<input type="checkbox"/> 2.	Friable ACM Surfacing Material	Damaged
<input type="checkbox"/> 3.	Friable ACM Surfacing Material	Significantly Damaged
<input type="checkbox"/> 4a.	Friable ACM Miscellaneous	Damaged
<input type="checkbox"/> b.	Friable ACM Miscellaneous	Significantly Damaged
<input type="checkbox"/> 5.	ACBM	Potential for Damage
<input type="checkbox"/> 6.	ACBM	Potential for Significant Damage
<input type="checkbox"/> 7.	Friable ACBM or Friable Suspected ACBM	Undamaged
<input checked="" type="checkbox"/> 8.	Non-Friable ACBM or Non-Friable Suspected ACM	

List General Functional Spaces e.g., Classrooms, Gym, Lunchroom

Water Tank room next to boiler room

General Condition of Entire Homogenous Area: Good Accessibility: Limited
 Potential For Disturbance: Limited Damage: 16 SF
 Type of Damage: Exposed glue dots on wall C
 Percent over Entire Homogenous Area: Unknown Known or Suspected Cause: Unknown
 Preventative Measures: N/A

**AHERA REINSPECTION
ASSESSMENT FORM**

Inspector Signature: CJ Karoly Project Number: 241801

Accreditation ID Number: 059567 Inspection Date: 7/11/2024

Building: Pine Forge Elementary School Homogenous Area: Blackboard Adhesive

Sample Numbers: N/A Homogenous Area I.D. Number: N/A

Friable: No Total Quantity: 73 EA

ACBM by: N/A Result: N/A

Classify ACBM and suspected ACBM assumed to be ACM into one of the following categories:

Category	Type Of Material	Condition
<input type="checkbox"/>	1a. Thermal System Insulation ACM	Damaged
<input type="checkbox"/>	b. Thermal system Insulation ACM	Significantly Damaged
<input type="checkbox"/>	2. Friable ACM Surfacing Material	Damaged
<input type="checkbox"/>	3. Friable ACM Surfacing Material	Significantly Damaged
<input type="checkbox"/>	4a. Friable ACM Miscellaneous	Damaged
<input type="checkbox"/>	b. Friable ACM Miscellaneous	Significantly Damaged
<input type="checkbox"/>	5. ACBM	Potential for Damage
<input type="checkbox"/>	6. ACBM	Potential for Significant Damage
<input type="checkbox"/>	7. Friable ACBM or Friable Suspected ACBM	Undamaged
<input checked="" type="checkbox"/>	8. Non-Friable ACBM or Non-Friable Suspected ACM	

List General Functional Spaces e.g., Classrooms, Gym, Lunchroom

700A, 700B, 701, 702, 703, 704, 705, 706, 707, 708, 709, 711, 713, 715, 717, 719

721, 722, 724, 726, Library Offices, Guidance, Instrument Room, Faculty Room 3

General Condition of Entire Homogenous Area: Good Accessibility: Limited

Potential For Disturbance: Limited Damage: N/A

Type of Damage: N/A

Percent over Entire Homogenous Area: N/A Known or Suspected Cause: N/A

Preventative Measures: N/A

**AHERA REINSPECTION
ASSESSMENT FORM**

Inspector Signature: CJ Karoly Project Number: 241801
 Accreditation ID Number: 059567 Inspection Date: 7/11/2024
 Building: Pine Forge Elementary School Homogenous Area: Floor tile and mastic
 Sample Numbers: N/A Homogenous Area I.D. Number: N/A
 Friable: No Total Quantity: 970 SF
 ACBM by: N/A Result: N/A

Classify ACBM and suspected ACBM assumed to be ACM into one of the following categories:

Category	Type Of Material	Condition
<input type="checkbox"/> 1a.	Thermal System Insulation ACM	Damaged
<input type="checkbox"/> b.	Thermal system Insulation ACM	Significantly Damaged
<input type="checkbox"/> 2.	Friable ACM Surfacing Material	Damaged
<input type="checkbox"/> 3.	Friable ACM Surfacing Material	Significantly Damaged
<input type="checkbox"/> 4a.	Friable ACM Miscellaneous	Damaged
<input type="checkbox"/> b.	Friable ACM Miscellaneous	Significantly Damaged
<input type="checkbox"/> 5.	ACBM	Potential for Damage
<input type="checkbox"/> 6.	ACBM	Potential for Significant Damage
<input type="checkbox"/> 7.	Friable ACBM or Friable Suspected ACBM	Undamaged
<input checked="" type="checkbox"/> 8.	Non-Friable ACBM or Non-Friable Suspected ACM	

List General Functional Spaces e.g., Classrooms, Gym, Lunchroom

Corridors outside Main Office, TV Studio (little room), Corridor outside Room 702

General Condition of Entire Homogenous Area: Good Accessibility: Limited
 Potential For Disturbance: Limited Damage: N/A
 Type of Damage: N/A
 Percent over Entire Homogenous Area: N/A Known or Suspected Cause: N/A
 Preventative Measures: N/A

**AHERA REINSPECTION
ASSESSMENT FORM**

Inspector Signature: CJ Karoly Project Number: 241801
 Accreditation ID Number: 059567 Inspection Date: 7/15/2024
 Building: Support Services Building Homogenous Area: Plaster
 Sample Numbers: N/A Homogenous Area I.D. Number: N/A
 Friable: yes Total Quantity: unknown
 ACBM by: N/A Result: N/A

Classify ACBM and suspected ACBM assumed to be ACM into one of the following categories:

Category	Type Of Material	Condition
<input type="checkbox"/> 1a.	Thermal System Insulation ACM	Damaged
<input type="checkbox"/> b.	Thermal system Insulation ACM	Significantly Damaged
<input type="checkbox"/> 2.	Friable ACM Surfacing Material	Damaged
<input type="checkbox"/> 3.	Friable ACM Surfacing Material	Significantly Damaged
<input type="checkbox"/> 4a.	Friable ACM Miscellaneous	Damaged
<input checked="" type="checkbox"/> b.	Friable ACM Miscellaneous	Significantly Damaged
<input type="checkbox"/> 5.	ACBM	Potential for Damage
<input type="checkbox"/> 6.	ACBM	Potential for Significant Damage
<input type="checkbox"/> 7.	Friable ACBM or Friable Suspected ACBM	Undamaged
<input type="checkbox"/> 8.	Non-Friable ACBM or Non-Friable Suspected ACM	

List General Functional Spaces e.g., Classrooms, Gym, Lunchroom

Basement Shop Area

General Condition of Entire Homogenous Area: Good Accessibility: Limited
 Potential For Disturbance: Limited Damage: 400 SF
 Type of Damage: Delaminating plaster throughout
 Percent over Entire Homogenous Area: unknown Known or Suspected Cause: Moisture
 Preventative Measures: Dehumidifier

**AHERA REINSPECTION
ASSESSMENT FORM**

Inspector Signature: CJ Karoly Project Number: 241801
 Accreditation ID Number: 059567 Inspection Date: 7/15/2024
 Building: Support Services Building Homogenous Area: Floor Tile
 Sample Numbers: N/A Homogenous Area I.D. Number: N/A
 Friable: No Total Quantity: 40 SF
 ACBM by: N/A Result: N/A

Classify ACBM and suspected ACBM assumed to be ACM into one of the following categories:

Category	Type Of Material	Condition
<input type="checkbox"/>	1a. Thermal System Insulation ACM	Damaged
<input type="checkbox"/>	b. Thermal system Insulation ACM	Significantly Damaged
<input type="checkbox"/>	2. Friable ACM Surfacing Material	Damaged
<input type="checkbox"/>	3. Friable ACM Surfacing Material	Significantly Damaged
<input type="checkbox"/>	4a. Friable ACM Miscellaneous	Damaged
<input type="checkbox"/>	b. Friable ACM Miscellaneous	Significantly Damaged
<input type="checkbox"/>	5. ACM	Potential for Damage
<input type="checkbox"/>	6. ACM	Potential for Significant Damage
<input type="checkbox"/>	7. Friable ACBM or Friable Suspected ACBM	Undamaged
<input checked="" type="checkbox"/>	8. Non-Friable ACBM or Non-Friable Suspected ACM	

List General Functional Spaces e.g., Classrooms, Gym, Lunchroom

Bathroom

General Condition of Entire Homogenous Area: Good Accessibility: Limited
 Potential For Disturbance: Limited Damage: 3 SF
 Type of Damage: cracked tiles
 Percent over Entire Homogenous Area: 10% Known or Suspected Cause: Unknown
 Preventative Measures: wax floors

AHERA REINSPECTION
ASSESSMENT FORM

Inspector Signature: CJ Karoly Project Number: 241801
 Accreditation ID Number: 059567 Inspection Date: 7/15/2024
 Building: Support Services Building Homogenous Area: Floor Tile
 Sample Numbers: N/A Homogenous Area I.D. Number: N/A
 Friable: No Total Quantity: 360 SF
 ACBM by: N/A Result: N/A

Classify ACBM and suspected ACBM assumed to be ACM into one of the following categories:

Category	Type Of Material	Condition
<input type="checkbox"/> 1a.	Thermal System Insulation ACM	Damaged
<input type="checkbox"/> b.	Thermal system Insulation ACM	Significantly Damaged
<input type="checkbox"/> 2.	Friable ACM Surfacing Material	Damaged
<input type="checkbox"/> 3.	Friable ACM Surfacing Material	Significantly Damaged
<input type="checkbox"/> 4a.	Friable ACM Miscellaneous	Damaged
<input type="checkbox"/> b.	Friable ACM Miscellaneous	Significantly Damaged
<input type="checkbox"/> 5.	ACBM	Potential for Damage
<input type="checkbox"/> 6.	ACBM	Potential for Significant Damage
<input type="checkbox"/> 7.	Friable ACBM or Friable Suspected ACBM	Undamaged
<input checked="" type="checkbox"/> 8.	Non-Friable ACBM or Non-Friable Suspected ACM	

List General Functional Spaces e.g., Classrooms, Gym, Lunchroom

Entrance Foyer

General Condition of Entire Homogenous Area: Good Accessibility: Limited
 Potential For Disturbance: Limited Damage: 20 SF
 Type of Damage: 20 SF cracked tiles by back door
 Percent over Entire Homogenous Area: 1% Known or Suspected Cause: Unknown
 Preventative Measures: wax floors

**AHERA REINSPECTION
ASSESSMENT FORM**

Inspector Signature: CJ Karoly Project Number: 241801
 Accreditation ID Number: 059567 Inspection Date: 7/15/2024
 Building: Support Services Building Homogenous Area: Floor Tile and Mastic
 Sample Numbers: N/A Homogenous Area I.D. Number: N/A
 Friable: No Total Quantity: 920 SF
 ACBM by: N/A Result: N/A

Classify ACBM and suspected ACBM assumed to be ACM into one of the following categories:

Category	Type Of Material	Condition
<input type="checkbox"/> 1a.	Thermal System Insulation ACM	Damaged
<input type="checkbox"/> b.	Thermal system Insulation ACM	Significantly Damaged
<input type="checkbox"/> 2.	Friable ACM Surfacing Material	Damaged
<input type="checkbox"/> 3.	Friable ACM Surfacing Material	Significantly Damaged
<input type="checkbox"/> 4a.	Friable ACM Miscellaneous	Damaged
<input type="checkbox"/> b.	Friable ACM Miscellaneous	Significantly Damaged
<input type="checkbox"/> 5.	ACBM	Potential for Damage
<input type="checkbox"/> 6.	ACBM	Potential for Significant Damage
<input type="checkbox"/> 7.	Friable ACBM or Friable Suspected ACBM	Undamaged
<input checked="" type="checkbox"/> 8.	Non-Friable ACBM or Non-Friable Suspected ACM	

List General Functional Spaces e.g., Classrooms, Gym, Lunchroom

Quigley Bus Office, Transportation Offices, Secretary's Office, Supervisor's Office, Bathroom

General Condition of Entire Homogenous Area: Good Accessibility: Limited
 Potential For Disturbance: Limited Damage: N/A
 Type of Damage: N/A
 Percent over Entire Homogenous Area: N/A Known or Suspected Cause: N/A
 Preventative Measures: N/A

**AHERA REINSPECTION
ASSESSMENT FORM**

Inspector Signature: CJ Karoly Project Number: 241801
 Accreditation ID Number: 059567 Inspection Date: 7/15/2024
 Building: Support Services Building Homogenous Area: Plaster
 Sample Numbers: N/A Homogenous Area I.D. Number: N/A
 Friable: yes Total Quantity: Unknown
 ACBM by: N/A Result: N/A

Classify ACBM and suspected ACBM assumed to be ACM into one of the following categories:

Category	Type Of Material	Condition
<input type="checkbox"/> 1a.	Thermal System Insulation ACM	Damaged
<input type="checkbox"/> b.	Thermal system Insulation ACM	Significantly Damaged
<input type="checkbox"/> 2.	Friable ACM Surfacing Material	Damaged
<input type="checkbox"/> 3.	Friable ACM Surfacing Material	Significantly Damaged
<input type="checkbox"/> 4a.	Friable ACM Miscellaneous	Damaged
<input type="checkbox"/> b.	Friable ACM Miscellaneous	Significantly Damaged
<input type="checkbox"/> 5.	ACBM	Potential for Damage
<input type="checkbox"/> 6.	ACBM	Potential for Significant Damage
<input checked="" type="checkbox"/> 7.	Friable ACBM or Friable Suspected ACBM	Undamaged
<input type="checkbox"/> 8.	Non-Friable ACBM or Non-Friable Suspected ACM	

List General Functional Spaces e.g., Classrooms, Gym, Lunchroom

Throughout 1st floor

General Condition of Entire Homogenous Area: Good Accessibility: Limited
 Potential For Disturbance: Limited Damage: N/A
 Type of Damage: N/A
 Percent over Entire Homogenous Area: N/A Known or Suspected Cause: N/A
 Preventative Measures: N/A

**AHERA REINSPECTION
ASSESSMENT FORM**

Inspector Signature: CJ Karoly Project Number: 241801
 Accreditation ID Number: 059567 Inspection Date: 7/10/2024
 Building: Washington Township Elementary Homogenous Area: Blackboard Adhesive
 Sample Numbers: N/A Homogenous Area I.D. Number: N/A
 Friable: No Total Quantity: 92 SF
 ACBM by: N/A Result: N/A

Classify ACBM and suspected ACBM assumed to be ACM into one of the following categories:

Category	Type Of Material	Condition
<input type="checkbox"/> 1a.	Thermal System Insulation ACM	Damaged
<input type="checkbox"/> b.	Thermal system Insulation ACM	Significantly Damaged
<input type="checkbox"/> 2.	Friable ACM Surfacing Material	Damaged
<input type="checkbox"/> 3.	Friable ACM Surfacing Material	Significantly Damaged
<input type="checkbox"/> 4a.	Friable ACM Miscellaneous	Damaged
<input type="checkbox"/> b.	Friable ACM Miscellaneous	Significantly Damaged
<input type="checkbox"/> 5.	ACBM	Potential for Damage
<input type="checkbox"/> 6.	ACBM	Potential for Significant Damage
<input type="checkbox"/> 7.	Friable ACBM or Friable Suspected ACBM	Undamaged
<input checked="" type="checkbox"/> 8.	Non-Friable ACBM or Non-Friable Suspected ACM	

List General Functional Spaces e.g., Classrooms, Gym, Lunchroom

Storage room, 9, 10, 12, 13, 23, 24, 48, 49, 51, 52, 53, 54, 55, 56, 57, 58, 60, 111, 112, 113, 114
121, 122, 123, 124, 131, 132, 133, 134, 141, 142, 143, 144, 151, 152, 153, 154, 161, 162, 163, 164

General Condition of Entire Homogenous Area: Good Accessibility: Limited
 Potential For Disturbance: Limited Damage: N/A
 Type of Damage: N/A
 Percent over Entire Homogenous Area: N/A Known or Suspected Cause: N/A
 Preventative Measures: N/A

**AHERA REINSPECTION
ASSESSMENT FORM**

Inspector Signature: CJ Karoly Project Number: 241801
 Accreditation ID Number: 059567 Inspection Date: 7/10/2024
 Building: Washington Township Elementary Homogenous Area: Fire Doors
 Sample Numbers: N/A Homogenous Area I.D. Number: N/A
 Friable: Yes Total Quantity: 13 Ea
 ACBM by: N/A Result: N/A

Classify ACBM and suspected ACBM assumed to be ACM into one of the following categories:

Category	Type Of Material	Condition
<input type="checkbox"/> 1a.	Thermal System Insulation ACM	Damaged
<input type="checkbox"/> b.	Thermal system Insulation ACM	Significantly Damaged
<input type="checkbox"/> 2.	Friable ACM Surfacing Material	Damaged
<input type="checkbox"/> 3.	Friable ACM Surfacing Material	Significantly Damaged
<input type="checkbox"/> 4a.	Friable ACM Miscellaneous	Damaged
<input type="checkbox"/> b.	Friable ACM Miscellaneous	Significantly Damaged
<input type="checkbox"/> 5.	ACBM	Potential for Damage
<input type="checkbox"/> 6.	ACBM	Potential for Significant Damage
<input checked="" type="checkbox"/> 7.	Friable ACBM or Friable Suspected ACBM	Undamaged
<input type="checkbox"/> 8.	Non-Friable ACBM or Non-Friable Suspected ACM	

List General Functional Spaces e.g., Classrooms, Gym, Lunchroom

Boiler Room, Room 12, Corridors

General Condition of Entire Homogenous Area: Good Accessibility: Limited
 Potential For Disturbance: Limited Damage: N/A
 Type of Damage: N/A
 Percent over Entire Homogenous Area: N/A Known or Suspected Cause: N/A
 Preventative Measures: N/A

SECTION C
CERTIFICATIONS



If found, please contact:
Department of Labor & Industry
Certification, Accreditation & Licensing Division
651 Boas Street, Room 1606
Harrisburg, PA 17121.
(717) 772-3396



21 00001574170
2018



If found, please contact:

Department of Labor & Industry
Certification, Accreditation & Licensing Division
651 Boas Street, Room 1606
Harrisburg, PA 17121.
(717) 772-3396