## **BOYERTOWN AREA SCHOOL DISTRICT**

## GILBERTSVILLE ELEMENTARY SCHOOL

AHERA 6 Month Re-Inspection Report

May 2023

Table 1
Room by Room Inventory of Asbestos Containing Materials

		MATERIAL												
BLDG	ROOM/AREA	DESCRIPTION	SAMP	QNTY	L	D		Α	Α	Р				
			NO		S	С	Е	Т	F	D	F	%	TYPE	COMMENTS
		Floor Tile and												
	Under Walls	Mastic	Α		S	0	0	0	0	1	1			Assumed
		Breeching												None Detected - NON
	Boiler Room	Insulation	B2	220	S							0		ASBESTOS
		Cloth HVAC												
		Expansion												Assumed - ends starting to
	Boiler Room	Joint	Α	1	Е	1	1	2	4	2	2			fray
		Blackboard												assumed, sample prior to
	Room 111	Adhesive	Α	3	Ε	0	4	2	0	1	2			removal
		Blackboard												assumed, sample prior to
	Room 112	Adhesive	Α	3	Ε	0	4	2	0	1	2			removal
		Blackboard												assumed, sample prior to
	Room 113	Adhesive	Α	3	Е	0	4	2	0	1	2			removal
		Blackboard												assumed, sample prior to
	Room 114	Adhesive	Α	3	E	0	4	2	0	1	2			removal
		Blackboard												assumed, sample prior to
	SGI Room	Adhesive	Α	3	E	0	4	2	0	1	2			removal
		Blackboard												assumed, sample prior to
	Room 121	Adhesive	Α	3	E	0	4	2	0	1	2			removal
		Blackboard												assumed, sample prior to
	Room 122	Adhesive	Α	3	Е	0	4	2	0	1	2			removal
		Blackboard												assumed, sample prior to
	Room 123	Adhesive	Α	3	E	0	4	2	0	1	2			removal
		Blackboard												assumed, sample prior to
	Room 124	Adhesive	Α	3	Е	0	4	2	0	1	2			removal
	Reading													
	Room - Room	Blackboard			_					l .				assumed, sample prior to
	26	Adhesive	Α	2	E	0	4	2	0	1	2			removal
	Faculty	Blackboard			_									assumed, sample prior to
	Lounge	Adhesive	Α	1	E	0	4	2	0	1	2			removal

#### Gilbertsville Elementary School 6-Month AHERA - May 2023

		MATERIAL												
BLDG	ROOM/AREA	DESCRIPTION	SAMP	QNTY	L	D		Α	Α	Р				
			NO		S	С	E	Т	F	D	F	%	TYPE	COMMENTS
		Blackboard												assumed, sample prior to
	Room 124	Adhesive	Α	3	Е	0	4	2	0	1	2			removal
		Blackboard												assumed, sample prior to
	Room 28	Adhesive	Α	2	E	0	4	2	0	1	2			removal
		Blackboard												assumed, sample prior to
	Room 30	Adhesive	Α	2	E	0	4	2	0	1	2			removal
		Blackboard												assumed, sample prior to
	Room 31	Adhesive	Α	1	E	0	4	2	0	1	2			removal
	Reading													
	Room adj. to	Blackboard												assumed, sample prior to
	Rm 30	Adhesive	Α	2	E	0	4	2	0	1	2			removal
		Blackboard			_			_	_					assumed, sample prior to
	Room 131	Adhesive	Α	2	E	0	4	2	0	1	2			removal
		Blackboard			_			_	_					assumed, sample prior to
	Room 132	Adhesive	Α	3	Е	0	4	2	0	1	2			removal
	D 400	Blackboard			_		١.,			١.,				assumed, sample prior to
	Room 133	Adhesive	Α	3	E	0	4	2	0	1	2			removal
	D 404	Blackboard			_		١,	0						assumed, sample prior to
	Room 134	Adhesive	Α	3	Е	0	4	2	0	1	2			removal
	D 405	Blackboard			_		١,	0						assumed, sample prior to
	Room 135	Adhesive	Α	3	E	0	4	2	0	1	2			removal
	Room 136 -	Diaglahaand												
	Computer	Blackboard	Λ .	3	Е			2		4	2			assumed, sample prior to
	Room	Adhesive Blackboard	Α	3		0	4		0	1	2			removal
	Room 130	Adhesive	Α	2	Е	0	4	2	0	1	2			assumed, sample prior to removal
	NOUII 130	Blackboard	^			0	4		U				1	assumed, sample prior to
	Room 137 - D	Adhesive	Α	1	Е	0	4	2	0	1	2			removal
	Room 137 - D	Blackboard		I		0	4		U					assumed, sample prior to
	LGI Room	Adhesive	Α	3	Е	0	4	2	0	1	2			removal
	2011(00111	Blackboard	/ \			-			"	<u> </u>				assumed, sample prior to
	Room 141	Adhesive	Α	2	Е	0	4	2	0	1	2			removal
	1100111 1-11	Blackboard	, ,			<b>│</b>	<del>                                     </del>			<u>'</u>				assumed, sample prior to
	Room 142	Adhesive	Α	2	Е	0	4	2	0	1	2			removal

### Gilbertsville Elementary School 6-Month AHERA - May 2023

		MATERIAL												
BLDG	ROOM/AREA	DESCRIPTION	SAMP	QNTY	L	D		Α	Α	Р				
			NO		S	С	E	Т	F	D	F	%	TYPE	COMMENTS
		Blackboard												assumed, sample prior to
	Room 143	Adhesive	Α	2	Ε	0	4	2	0	1	2			removal
		Blackboard												assumed, sample prior to
	Room 144	Adhesive	Α	2	E	0	4	2	0	1	2			removal
		Blackboard												assumed, sample prior to
	Kindergarten 1	Adhesive	Α	2	Е	0	4	2	0	1	2			removal
		Blackboard												assumed, sample prior to
	Kindergarten 2	Adhesive	Α	2	Е	0	4	2	0	1	2			removal
		Blackboard	_		_			_	_					assumed, sample prior to
	Room 151	Adhesive	Α	2	E	0	4	2	0	1	2			removal
		Blackboard	_		_			_	_					assumed, sample prior to
	Room 152	Adhesive	Α	2	E	0	4	2	0	1	2			removal
		Blackboard			_			_	_					assumed, sample prior to
	Room 153	Adhesive	Α	2	E	0	4	2	0	1	2			removal
		Blackboard			_			_	_					assumed, sample prior to
	Room 154	Adhesive	Α	2	E	0	4	2	0	1	2			removal
		Blackboard			_									assumed, sample prior to
	Room 161	Adhesive	Α	2	Е	0	4	2	0	1	2			removal
	D 400	Blackboard			_		١.,							assumed, sample prior to
	Room 162	Adhesive	Α	2	Е	0	4	2	0	1	2			removal
	D 400	Blackboard			_		١,							assumed, sample prior to
	Room 163	Adhesive	Α	2	Е	0	4	2	0	1	2			removal
	Danis 404	Blackboard	^		_		_							assumed, sample prior to
	Room 164	Adhesive	Α	2	E	0	4	2	0	1	2			removal
	Librani	Blackboard Adhesive	۸		Е			2		1	2			assumed, sample prior to
	Library	Blackboard	Α	2		0	4		0	l l	2			removal
	Music Room	Adhesive	Α	2	Е	0	4	2	0	1	2			assumed, sample prior to removal
	Instrumental	Blackboard			<u> </u>	0	4		U	ı				assumed, sample prior to
	Music	Adhesive	Α	3	Е	0	4	2	0	1	2			removal
	Faculty Dining	Blackboard		3	<u> </u>	-	-		U	- 1				assumed, sample prior to
	Room	Adhesive	Α	1	Е	0	4	2	0	1	2			removal
	1100111	Blackboard	, ,	'		<b> </b>				'				assumed, sample prior to
	Art Room	Adhesive	Α	3	Е	0	4	2	0	1	2			removal
	Art Room	Adhesive	А	3	E	U	4	2	U	1	2			removal

#### Gilbertsville Elementary School 6-Month AHERA - May 2023

BLDG	ROOM/AREA	MATERIAL DESCRIPTION	SAMP	QNTY	ı	D		Α	Α	Р				
5250	1.00m/Z/	DEGGINI HOIL	NO	Q.(1.1	S	С	Е	T	F	D	F	%	TYPE	COMMENTS
	Library Office	Blackboard Adhesive	А	2	E	0	4	2	0	1	2			assumed, sample prior to removal
	Boiler Room	Fire Doors	Α	2	Е	0	2	1	1	1	1	Α		assumed - good condition
	Room outside Boiler Room	Fire Doors	A	2	E	0	2	1	1	1	1	Α		assumed - good condition
	Music Room Corridors	Fire Doors	А	4	E	0	2	1	1	1	1	А		assumed - good condition
	Basement Rooms	Fire Doors	А	12	E	0	2	1	1	1	1	А		assumed - good condition

This AHERA 6 Month Re-Inspection was performed by Scott Schiel in May 2023 (#754246)

Table 2
Summary of ACM

Material	Estimated		Estimated	
Description	Quantity		Removal Cost	
Floor Tile and Mastic	Unknown	S		
<b>HVAC Cloth Vibration Joints</b>	1	Each	\$100	
Blackboard Adhesive	116	Each	\$34,800	
Fire Doors	7	Each	\$2,100	
·				
ESTIMATED TOTAL			\$37,000	

Table 3
Recommended Response Actions

Location	Material Description	Recommended Response Action
Under Walls	Floor Tile and Mastic	Handle under O & M Program - Sample prior to removal
Boiler Room	HVAC Cloth Vibration Joints	Handle under O & M Program - Sample prior to removal
Throughout Building	Blackboard Adhesive	Handle under O & M Program - Sample prior to removal
Throughout Building	Fire Doors	Handle under O & M Program - Sample prior to removal

# Table 4 Summary of Response Actions Taken

There has been no known or documented asbestos response actions performed in Gilbertsville Elementary School since the last AHERA 3 Year Re-Inspection, which was conducted in November 2021.