

***BOYERTOWN AREA SCHOOL DISTRICT***

***SENIOR HIGH SCHOOL***

***AHERA 6 Month Re-Inspection Report***

***November 2023***

**Table 1**  
**Room by Room Inventory of Asbestos Containing Materials**

FLR	ROOM/AREA	MATERIAL DESCRIPTION	SAMP	QNTY	L	D		A	A	P				
			NO		S	C	E	T	F	D	F	%	TYPE	COMMENTS
2	Stairwell #1	Fire Doors		2	Each	0	2	1	1	1	1	A		remains - good condition
3	Stairwell #1	Fire Doors		2	Each	0	2	1	1	1	1	A		remains - good condition

*This AHERA 6 Month Re-Inspection was performed by Scott Schiel in November 2023 (#754246)*

Scott Schiel #754246  
 Director of Facilities & Operations  
 Boyertown Area School District

**Table 2**  
**Summary of ACM**

<b>Material Description</b>	<b>Estimated Quantity</b>		<b>Estimated Removal Cost</b>
Mastic under 12" x 12" Floor Tile	0 *		\$0
9" x 9" Floor Tile and Mastic	0 *		\$0
Mastic under Carpet	0 *		\$0
Sheet Vinyl Flooring	0 *		\$0
Layered Paper Pipe Insulation	0 *		\$0
Blackboard/Coarkboard Adhesive	0 *		\$0
Fire Doors	4		2000 per
Wall Plaster	0 *		\$0
Cloth Vibration Joints	0 *		\$0
Transite Panels	0 *		\$0
<b>ESTIMATED TOTAL</b>			<b>\$0</b>
<b>* Abated in January-February 2016</b>			

Scott Schiel #754246  
Director of Facilities & Operations  
Boyertown Area School District

***Table 3***  
***Recommended Response Actions***

<b><i>Location</i></b>	<b><i>Material Description</i></b>	<b><i>Recommended Response Action</i></b>
Throughout Building	Fire Doors	Material to be removed prior to renovations

Scott Schiel #754246  
Director of Facilities & Operations  
Boyertown Area School District

***Table 4***  
***Summary of Response Actions Taken***

There were no known asbestos response actions performed in Boyertown Area Senior High School since the last AHERA 3 Year Re-Inspection, which was conducted in November 2021.