

BOYERTOWN AREA SCHOOL DISTRICT

SENIOR HIGH SCHOOL

AHERA 6 Month Re-Inspection Report

May 2022

**TABLE 1 - ROOM BY ROOM INVENTORY OF ASBESTOS CONTAINING MATERIALS - BOYERTOWN SENIOR HIGH SCHOOL
May 2022 AHERA INSPECTION**

FLR	ROOM/AREA	MATERIAL DESCRIPTION	SAMP NO	QNTY	L S	D C	E	A T	A F	P D	F D	%	TYPE	COMMENTS
2	Stairwell #1	Fire Doors		2	Each	0	2	1	1	1	1	A		remains - good condition
3	Stairwell #1	Fire Doors		2	Each	0	2	1	1	1	1	A		remains - good condition
	<i>The AHERA 6 Month Re-Inspection was performed by Scott Schiel in May 2022</i>													

TABLE 2**BOYERTOWN AREA SENIOR HIGH SCHOOL
SUMMARY OF ACM**

<i>Material Description</i>	<i>Estimated Quantity</i>		<i>Estimated Removal Cost</i>
Mastic under 12" x 12" Floor Tile	0 *		\$0
9" x 9" Floor Tile and Mastic	0 *		\$0
Mastic under Carpet	0 *		\$0
Sheet Vinyl Flooring	0 *		\$0
Layered Paper Pipe Insulation	0 *		\$0
Blackboard/Coarkboard Adhesive	0 *		\$0
Fire Doors	4		\$1,000
Wall Plaster	0 *		\$0
Cloth Vibration Joints	0 *		\$0
Transite Panels	0 *		\$0
<i>ESTIMATED TOTAL</i>			<i>\$1,000</i>
<i>* Abated in January-February 2016</i>			

TABLE 3
RECOMMENDED RESPONSE ACTIONS
BOYERTOWN AREA SENIOR HIGH SCHOOL

<i>Location</i>	<i>Material Description</i>	<i>Recommended Response Action</i>
Throughout Building	Fire Doors	Material to be removed prior to renovations

TABLE 4

***SUMMARY OF RESPONSE ACTIONS TAKEN
BOYERTOWN AREA SENIOR HIGH SCHOOL***

There were no known asbestos response actions were performed in Boyertown Area Senior High School since the last AHERA 3 Year Re-Inspection, which was conducted in December 2019.