

BOYERTOWN AREA SCHOOL DISTRICT

SENIOR HIGH SCHOOL

AHERA 6 Month Re-Inspection Report

May 2023

Table 1
Room by Room Inventory of Asbestos Containing Materials

FLR	ROOM/AREA	MATERIAL DESCRIPTION	SAMP	QNTY	L	D		A	A	P				
			NO		S	C	E	T	F	D	F	%	TYPE	COMMENTS
2	Stairwell #1	Fire Doors		2	Each	0	2	1	1	1	1	A		remains - good condition
3	Stairwell #1	Fire Doors		2	Each	0	2	1	1	1	1	A		remains - good condition

This AHERA 6 Month Re-Inspection was performed by Scott Schiel in May 2023 (#754246)

Scott Schiel #754246
Director of Facilities & Operations
Boyertown Area School District

Table 2
Summary of ACM

Material Description	Estimated Quantity		Estimated Removal Cost
Mastic under 12" x 12" Floor Tile	0 *		\$0
9" x 9" Floor Tile and Mastic	0 *		\$0
Mastic under Carpet	0 *		\$0
Sheet Vinyl Flooring	0 *		\$0
Layered Paper Pipe Insulation	0 *		\$0
Blackboard/Coarkboard Adhesive	0 *		\$0
Fire Doors	4		2000 per
Wall Plaster	0 *		\$0
Cloth Vibration Joints	0 *		\$0
Transite Panels	0 *		\$0
ESTIMATED TOTAL			\$0
* Abated in January-February 2016			

Scott Schiel #754246
Director of Facilities & Operations
Boyertown Area School District

Table 3
Recommended Response Actions

<i>Location</i>	<i>Material Description</i>	<i>Recommended Response Action</i>
Throughout Building	Fire Doors	Material to be removed prior to renovations

Table 4
Summary of Response Actions Taken

There were no known asbestos response actions performed in Boyertown Area Senior High School since the last AHERA 3 Year Re-Inspection, which was conducted in November 2021.